


Assemblies Affected: D5RH and DPC100 (DIGI-5)
Symptom: Requirement for doorbell paging.
Cause: Contact closure (CC12) required.



File name: D5RH_DPC100
Rev.2 3/23/10
cbevando